

ST PETER'S TOWER CLOCK



**PRIOR TO COMMENCING THE
REPAIR AND REFURBISHMENT
OF THE CLOCK THE TOWER WAS
IN NEED OF REPAIR. IT NEEDED
TO BE MADE WATERTIGHT AND
A SAFE ENVIRONMENT FOR THE
CLOCK COMPANY TO WORK IN.**

New tiles
on the
tower roof



A photograph showing the interior of a clock chamber. The wall is made of dark, rough-hewn bricks. A horizontal copper pipe runs across the upper part of the wall. A wooden plank is positioned vertically in the foreground. To the right, a diagonal wooden beam is visible. Several cylindrical metal weights are stacked on a ledge against the brick wall. The floor is made of light-colored stone or concrete.

The clock chamber before



**NEW FALSE
FLOOR**



**NEW
WINDOWS
IN THE
TOWER**









Caution
Men
Working
Overhead

LEADING EDGE
SOLUTIONS

ROPE ACCESS
CONTRACTORS

07415 886036





































































Item No: 02
Description: 1 p...
Rattan: grey
F...
G.W: 20
L.W: 20
KgS
Meas: 157X37X...
Batch No: 001
MADE IN CHINA





THE COST OF THE TOWER REPAIRS
AND THE REPAIR AND
REFURBISHMENT OF THE CLOCK HAS
BEEN FUNDED BY THE ESTATE OF THE
LATE ANN RICHARDSON A FORMER
PEDMORE RESIDENT.

ST PETER'S AND ON BEHALF OF THE
COMMUNITY OF PEDMORE ARE MOST
GRATEFUL FOR THIS GENEROUS GIFT.